

Designer

Create New Job	Ctrl + N
Open Saved Job	Ctrl + O
Quickly Save a Job	Ctrl + S
Undo (Work in Progress)	Ctrl + Z
Cut	Ctrl + X
Copy	Ctrl + C
Paste	Ctrl + V
Delete Text	Delete
Job Information Window	Ctrl + I
Draw Walls Screen	F5
Place Cabinets Screen	F6
Edit Elevations Screen	F7
Take the Tour	F8
Adjust Job Standards	Ctrl + A
Job Costing	Ctrl + J
Delete Cabinets	Ctrl + Delete
Edit Material Lists	Shift + M
Edit Material Properties	Ctrl + M
Contextual Help File	F1
Zoom In	Mouse Wheel Forward
Zoom Out	Mouse Wheel Backward

Move Image Around:

Hold Right Mouse Button down and move the mouse around

Quick Move:

Right Click on a cabinet on the place cabinets screen and then left click to quickly move it around

CNC Workshop

Import from Designer	F5
Cut	Ctrl + X
Copy	Ctrl + C
Paste	Ctrl + V
Delete Text	Delete
Select All	Ctrl + A
Select None	Ctrl + D
Select by Material	Ctrl + M
Select by Part Type	Ctrl + T
Select by Cabinet Type	Ctrl + B
Find	Ctrl + F
Board Routing	F6
Dado Routing	F7
Material and Tools Settings	F8
Real Material Thicknesses	F9
Panel Hole Pattern Standards	F10
Opening Standards	F11
Door Hinges	F12
Zoom In	Mouse Wheel Forward
Zoom Out	Mouse Wheel Backward

Tour

Move Camera Forward	W or Up Arrow on Keyboard
Move Camera Backward	S or Down Arrow on Keyboard
Rotate Camera Left	A or Left Arrow on Keyboard
Rotate Camera Right	D or Right Arrow on Keyboard
Shift/Strafe Camera Left	Right Mouse Button + A (or Left Arrow on Keyboard)
Shift/Strafe Camera Right	Right Mouse Button + D (or Right Arrow on Keyboard)
Raise Camera View Up	Q
Lower Camera View Down	E
Show/Hide UI	Space Bar
Close Program	Esc